

Solution	Specific solutions
Increased visibility	<ul style="list-style-type: none">• Require workers to wear high-visibility safety apparel, including fluorescent, brightly colored, and reflective apparel, vests with strobes, and illumination rings for hard hats^{1a,1b,3}• Employ work zone lighting, glare-free if possible^{1c,2}• Increase taper length³• Install